

information on a random basis, this temperature reading probably doesn't represent the maximum indicated battery temperature.




Photo 2: The downward spike indicates a battery temperature of -198° F, which is cold, even for Antarctica!